Purfling Groove

Splints or purfling are laid into the channel which must be marked first with a purfling groove marker and then carved with a carving instrument. The carving of the channel is done with a purfling groove chisel, a cranked instrument with a sharp blade at the underside to assure a smooth and even channel surface.

back